

This PTAW hardfaced dragline bucket adaptor has only lasted for 2 weeks. ARM HF options last 6 months on this mine site and can then be rebuilt for 50% of new cost.

NOT an Abrasion Resistant Materials Pty Ltd product



**ABRASION
RESISTANT
MATERIALS** PTY
LTD